GUBI[®]

CDC.1 LOUNGE CHAIR UPHOLSTERED // WOOD BASE Designed by Carlo de Carli

CARLO DE CARLI COLLECTION

PRODUCT

COLORS



American Walnut - high gloss

Missing picture



Black Oak - high gloss

Brown Stained Birch - high

DESCRIPTION

A fine sense for modern material, design and industry and a willingness to experiment and invent, characterizes Carlo De Carli's contribution to postwar architecture and design, and earned him a reputation as one of the greatest masters of Italian design.

The CDC. collection consist of upholstered lounge chair and sofa with wooden legs. The legs are made from turned solid wood and are available in glossy walnut, glossy black painted oak and glossy brown stained birch. The chair is always fully upholstered in fabric or leather. **VERSION - FULL-UPHOLSTERED**

- Upholstered in fabric/ lacquered American Walnut /

- Upholstered in fabric/ lacquered Black painted Oak / - Upholstered in fabric/ lacquered Brown stained Birch /

CHAIR VERSION

Order item - look for part number in the pricelist.

The series consists of the following:

CDC.1 Sofa CDC.1 Lounge chair

760 820 720

FACTS

MEASUREMENT - W x D x H mm Sitting height: 300 mm Seat width: 480 mm Seat depth: 530 mm Seat height: 380 mm Chair width: 720 mm Chair depth: 820 mm Chair height: 760 mm Armrest height: 530 mm

WEIGHT ITEM 20,3 kg

PACKAGING TYPE Cardboard box

PACKAGING MEASUREMENT - L x W x H CM 74x84x80 cm

WEIGHT PACKAGING - MATERIAL TYPE

- Delivery note

- Cardboard box, FEFCO quality EB85BB

- Cardboard extra bottom - Polybag PE

- LD-EPE foam protector

- Strapping

WEIGHT PACKAGING - TOTAL 3 kg

NUMBER OF PARCELS 1 pcs.

CDC.1 LOUNGE CHAIR UPHOLSTERED // WOOD BASE Designed by Carlo de Carli

CARLO DE CARLI COLLECTION

GUBI[®]

ACCESSORIES

FABRIC/LEATHER CONSUMPTION

- Fabric: 140 cm x 3,4 m

CLEANING AND MAINTENANCE

For cleaning the upholstered surface, first try to brush off the dirt gently. If this is not enough then vacuum the surface. If further cleaning of the padding is needed, a stain remover is recommended. The cleaning has to be gentle and must always be tested on the most invisible area of the surface before the actual cleaning. Avoid blotches by gentle, circular rubbing towards the stain. To avoid stains, quickly remove the dirt with a piece of absorbing household wipe and clean with water and colourless washing-up liquid.

Do not use the following products for the padding: • Undiluted cleaning liquids.

- Bleach.
 Ammoniac.

Soap for hard surfaces.

TESTS

CERTIFICATION AND LABELS